



Visor



42-0206 Chrome Light Visors designed smartly and are easy-to-install.

Headlamp (each)

VT No. Type

42-0200 7" FLH

42-0209 1947-59 Headlight

42-0201 5" XL-FX Bates Headlight

Spotlamp (pair)

42-0202 4" FLH

33-1316 4.5" Tech Glide

Turn Signal (pair)

42-0203 1973-85 FX-XL

42-9925 1963-85 FL

42-9941 1986-up FLT Front

42-9942 1986-up FX-XL

42-0199 1986-up FLT, Rear

Bullet Lamp (pair)

42-0204 1 3/4"

Tail Lamp (each)


42-0205 1947-54 Tombstone

42-0206 1955-72 FL-XL

42-0216 1973-up FL-FX-XL

42-9966 As Above Louvered

42-0000 FXWG-FXST Tail Lamp









Visors
42-0200
and 42-0202
installed



42-9925
Signal Lamp

Gaskets



Turn Signal/Fender Light/ Tail Lamp Gaskets

GB Stock	GB Beaded	Fits
—	15-0289	1968-84 Front Fender Lamp
15-0303	—	1960-84 FL Headlamp Mt Ring
15-0206	—	1973-up Tail Lamp Lens
15-0302	—	1955-72 Tail Lamp Top Lens
15-0301	—	1955-72 Tail Lamp Lens
15-0224	15-0207	1973-up Tail Lamp Mounting
15-0742	—	1968-85 FL Turn Signal Lens
15-0723	—	Front Fender Lamp
15-0187	—	1973-85 FX-XL Turn Signal Lens
—	15-0577	Sport Tail Lamp Mounting
15-0665	—	Cateye Tail Lamp Lens
15-0709	—	Sparto Tail Lamp Mounting

Ever soldered a LED into your project backward? It can really mess up a good day! If you don't know, LED's have a positive side and a negative side, and will only light up when wired correctly. Most LED's have one longer lead to indicate the polarity, but not all.

Did you know?

LED lights are polarity sensitive. It is a smart idea to test LED assemblies, is not color coded prior to assembly.

LED Polarity

Ever soldered a LED into your project backward it can really mess up a good day! If you don't know, LED's have a positive and a negative side, and will only light when wired correctly. Most LED's have one longer lead to indicate the polarity, but not all.

Warranty

LED Boards will be warranted only. No credit will be issued on any lamps or components with the 33 prefix. Lamps will either be exchanged or repaired and returned to the dealer.