




# CV Keihin Carburetor



**Keihin Carburetor Rebuilds** contain needle, proper o-rings and diaphragm.

VT No.	Year	Brand
35-0200	1976-78	GB
35-0240	1976-86	Keihin
35-0196	1983-89	GB
35-0219	1976-86	James
35-0416	1989-up CV	GB
35-0422	1988-up CV	James



**ThunderJet Accelerator Jet & Accessories** mounts in all Bendix-Keihin, S&S, flowmaster, Tillotson, and CV carburetors. Choke must be deleted for use. Works on Venturi vacuum principle as third jet. Extra jets included.

VT No.	Type
35-1972	ThunderJet Bendix Keihin, S&S E series
35-1976	ThunderJet for CV. Carburetor
35-0179	ThunderJet for S&S G & D Carburetor
35-9244	Replacement Jet Tube



**Deluxe Carburetor Kits** include all pieces shown for 1976-89 Keihin carburetors.

VT No.	Type
35-9172	Stock
35-9176	Viton
35-9279	Replica

**Keihin Low Speed Jets** fit 1976-89 Keihin carburetors, except CV.

VT No.	OEM	MM
35-0297	27896-79	.65
35-0294	27894-78	.68
35-0296	27897-78	.72
35-0295	27382-77	.75
35-0299	27348-77	.88
35-0298	27348-76	1.00



**Keihin Carburetor Fitting** replaces 27371-76, 90°, plastic, each.  
VT No. 40-0534



**Adjustable Idle Mixture Needles** provide adjustment for Keihin carburetors. Fits CV type.  
VT No. 35-0130

**Keihin Main Jets.**

VT No.	OEM	MM
35-0357	27419-76	1.65
35-0358	27418-76	1.70
35-0359	27417-76	1.75
35-0361	27416-76	1.80



**Accelerator Pump Kit** improves throttle response on 1979-88 type Keihin carburetor models with a greater volume of fuel from the pump circuit.  
VT No. 35-9050




**Slow Jet Screw Driver** facilitates removal of Keihin slow jets with no damage to jet.  
VT No. 16-0546




**Keihin Adjustable Main Jet.** Full adjustability for maximum tuning efficiency.  
VT No. 35-0369




35-0230



**High Flow Fuel Inlet** replaces broken fuel inlet to the carburetor bowl for modified engines. Fits all Keihin carburetors (Butterfly and CV) 1976-up Shovelhead, Evolution, TC-88.  
VT No. 35-0134



**Carburetor Mount Stud Set** replaces 29254-78. Fits 1978-89. Length is 1 1/4"  
VT No. 12-2110



**Enricher for CV Carburetors** will eliminate choke cable. Unit has three positions.  
VT No. 35-0447



**Needle Jet Seat Cutter** eliminates gasoline seepage from around the needle jet. Creates a smooth and concentric seat  
VT No. 16-0095

## Keihin Carburetor Parts and Accessories

VT No.	#	OEM	Item
14-0921	A	27121-89	Float Valve O-ring 1989-up CV
35-0110	B	27311-76	Pump cap, 10 pack
14-0566		27312-76	Float Bowl Screw O-ring, 1976-77
13-9234	C	27314-76	Throttle Stop Screw Spring
14-0560	D	27324-83	Float bowl O-ring 1983-91 CV, 5 pk
35-9067	E	27337-76	Float valve with clip
		27338-76	
35-0230	F	27585-88	Vacuum Piston
14-0559	G	27358-76	Float bowl O-ring 1976-78
35-9066	I	27361-76	Pump diaphragm
35-0852	I	27361-76	Pump diaphragm (5 pack)
13-9168		27362-76	Diaphragm spring
14-0564	K	27577-88	Float bowl O-ring 1989-91 CV
14-0937	K	27577-92	Float bowl O-ring 1992-up CV
14-0557	L	27889-78	Float bowl O-ring 1978-82
14-0679	M	27385-76	Low Speed Jet Plug 1976-up
13-9212		27123-89	Accelerator Rod Spring 1989-up
13-9169		27136-81	Throttle and Idle Adj. Screw Spring, 1981-up
		27136-90	Idle Screw Spring 1990-up
13-9213		27162-89	Vacuum Piston Spring, 1989-up
13-9179		27315-88	Primary Starter Spring, 1988-up
13-9181		27319-76	Low Speed Adjuster Screw Spring, 1981-up
13-9183		27322-76	Throttle Lever Spring, 1981-up
13-9178		27584-88	Primary Vacuum Spring, 1988-up
35-9111		27886-78A	Needle for Screamin' Eagle
35-9196	N	27576-92	Float 40 mm CV 1992-up